


General Information

Date & Time: 04, Feb, 2025 14:51

Make	Toyota	Model	Vios
YOM	2022	Mileage	76,612
Registration No.	NEM3776	Chassis No.	PA1B18F35N4171143
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.0	113	123	118
2	Boot Lid	276.3	223	423	183
3	Roof	101.8	106	98	96/107
4	Left Front Fender	102.3	101	104	102
5	Left Front Door	107.3	112	104	106
6	Center Panel Left				
7	Left Rear Door	103.8	106	98	107
8	Left Back Panel	110.6	121	109	102
9	Right Front Fender	155.3	171	137	158
10	Right Front Door	164.0	167	156	169
11	Center Panel Right				
12	Right Rear Door	195.6	230	147	210
13	Right Back Panel	166.3	151	150	198

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Worn, Scratch, Cut, Crack - Large	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Dent - Minimal / (L) Mirror - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Door, Molding - Dent - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Dent - Minimal / (R) Rear Fender, Molding - Scratch - Small / Roof - Dent - Minimal / (R) Step, In-panel, Side Spoiler - Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate number/ with spare tire/jack/incomplete tool/with warranty booklet/abnormal engine noise