

General Information

Date & Time: 04, Feb, 2026 10:51

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	86,985
Registration No.	NHS3405	Chassis No.	PA1B18F39R4259425
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.0	118	120	116
2	Boot Lid	112.0	102	118	116
3	Roof	110.3	141	99	102/99
4	Left Front Fender	104.8	91	113	110
5	Left Front Door	93.6	97	93	91
6	Center Panel Left				
7	Left Rear Door	105.3	120	100	96
8	Left Back Panel	104.3	111	102	100
9	Right Front Fender	98.3	98	95	102
10	Right Front Door	109.4	133	100	95
11	Center Panel Right				
12	Right Rear Door	112.3	114	113	110
13	Right Back Panel	112.3	119	108	110

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Worked - Large / (L) Front Seat - Grime - Medium</p>	<p>Remarks (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Dent - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>with warranty booklet, with jack and tools, Sparetire, LTO PLATE available -inspected by Jomar</p>