

General Information

Date & Time: 02, Feb, 2025 13:21

Make	Toyota	Model	Vios
YOM	2022	Mileage	36,970
Registration No.	NHC3912	Chassis No.	PA1B18F35N4191490
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	191.3	172	219	183
2	Boot Lid	168.6	207	143	156
3	Roof	103.5	107	106	99/102
4	Left Front Fender	157.6	155	167	151
5	Left Front Door	111.3	113	115	106
6	Center Panel Left				
7	Left Rear Door	140.6	144	149	129
8	Left Back Panel	110.3	118	111	102
9	Right Front Fender	94.3	81	99	103
10	Right Front Door	148.6	138	137	171
11	Center Panel Right				
12	Right Rear Door	109.3	100	111	117
13	Right Back Panel	116.3	106	116	127

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Console, Switches, Vents - Traces of Adhesive Tape - Yes	Remarks Bonnet - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch - Large / Front Bumper, Grille, Lamps - Scratch - Large / (R) Rear Fender, Molding - Dent - Small / (L) Rear Fender, Molding - Dent - Small / Roof - Dent - Minimal / (L) Front Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with LTO plate number/spare tire/ jack/incomplete tools/No reverse camera/No warranty booklet /worn tires