

## General Information

Date & Time: 04, Feb, 2026 12:58

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	7,349
<b>Registration No.</b>	NKS9239	<b>Chassis No.</b>	PA1B18F31S4289377
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red Mica Metallic		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.0	113	102	112
2	Boot Lid	114.3	111	110	122
3	Roof	102.3	108	106	98/97
4	Left Front Fender	99.3	97	97	104
5	Left Front Door	99.4	100	99	99
6	Center Panel Left				
7	Left Rear Door	102.2	105	104	98
8	Left Back Panel	102.7	116	100	92
9	Right Front Fender	102.0	107	99	100
10	Right Front Door	100.2	105	97	98
11	Center Panel Right				
12	Right Rear Door	105.6	101	109	107
13	Right Back Panel	101.6	99	102	104

**Overall Evaluation :**

B

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	A	<b>Exterior Evaluation :</b>	D
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Ceiling - Grime - Minimal / Rear Seat - Grime - Minimal</p>		<p><b>Remarks</b> (R) Front Fender, Molding - Scratch &amp; Dent - Small / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Small / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / (L) Rear Fender, Molding - Scratch &amp; Dent - Small / (L) Rear Door, Molding - Scratch &amp; Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Minimal / (L) Front Door, Molding - Scratch &amp; Dent - Small / Roof - Scratch &amp; Dent - Minimal / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Bonnet, Headlight - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Defects not found</p>	

<b>Inspector Notes</b>
with LTO plate ,with warranty and manual booklet, with incomplete tools and jack, with reverse camera ,with spare tire and key, scratches issue.