


General Information

Date & Time: 04, Feb, 2025 15:52

Make	Toyota	Model	Vios
YOM	2022	Mileage	48,371
Registration No.	DAR7306	Chassis No.	PA1B18F3XN4185958
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.6	116	108	120
2	Boot Lid	110.6	107	113	112
3	Roof	103.2	98	93	94/128
4	Left Front Fender	117.3	102	108	142
5	Left Front Door	104.2	111	102	100
6	Center Panel Left				
7	Left Rear Door	104.3	110	103	100
8	Left Back Panel	108.3	116	103	106
9	Right Front Fender	123.2	167	100	103
10	Right Front Door	97.9	95	96	103
11	Center Panel Right				
12	Right Rear Door	104.8	97	111	106
13	Right Back Panel	102.9	97	101	111

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Grime - Small / (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Large / Rear Seat - Grime - Large / Trunk Room - Worked - Large	Remarks Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Step, In-panel, Side Spoiler - Dent - Large / (R) Front Door, Molding - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (L) Front Fender, Molding - Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Medium / Roof - Dent - Small / (R) Rear Door, Molding - Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

With LTO plate number/with spare tire / jack and tools/with warranty booklet/No reverse camera