

General Information

Date & Time: 01, Feb, 2025 14:48

Make	Toyota	Model	Vios
YOM	2021	Mileage	61,538
Registration No.	NEL2378	Chassis No.	PA1B18F30M4143197
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	136.3	172	111	126
2	Boot Lid	109.6	106	107	116
3	Roof	104.7	107	101	105/106
4	Left Front Fender	105.3	102	104	110
5	Left Front Door	108.0	108	113	103
6	Center Panel Left				
7	Left Rear Door	189.3	179	188	201
8	Left Back Panel	154.0	161	149	152
9	Right Front Fender	110.0	116	106	108
10	Right Front Door	113.0	110	115	114
11	Center Panel Right				
12	Right Rear Door	106.6	103	105	112
13	Right Back Panel	111.6	104	112	119

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat Head Rest - Worked - Small / (L) Front Seat - Worn - Yes	Remarks (L) Rear Door - Repair Traces - Yes / (R) Rear Fender, Molding - Dent - Small / Roof - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Bonnet, Headlight - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Dent - Minimal / (R) Front Door, Molding - Dent - Minimal / (L) Front Door, Molding - Dent - Minimal / (L) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate number/spare tire/jack/incomplete tools/No reverse camera/No warranty booklet/with leather seat cover.