


General Information

Date & Time: 04, Feb, 2025 15:37

Make	Toyota	Model	Wigo
YOM	2021	Mileage	39,461
Registration No.	NDZ5404	Chassis No.	MHKA4DF5FMJ055587
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	77.3	79	83	70
2	Boot Lid	85.9	85	84	88
3	Roof	67.9	56	70	83/62
4	Left Front Fender	81.8	89	78	79
5	Left Front Door	82.9	83	81	85
6	Center Panel Left				
7	Left Rear Door	85.5	91	83	83
8	Left Back Panel	68.3	73	69	63
9	Right Front Fender	78.9	75	81	81
10	Right Front Door	84.7	86	87	81
11	Center Panel Right				
12	Right Rear Door	84.0	92	78	82
13	Right Back Panel	80.1	80	75	86

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Grime - Large / Carpet - Worn, Scratch, Cut, Crack - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes	Remarks Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / (R) Center Panel - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Roof - Scratch - Small / (R) Mirror - Crack - Damaged
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Lamps (Brake, Tail, Fog) - Issue - Yes

Inspector Notes
with warranty booklet/ incomplete tools/ no spare tire/ no jack/ right side mirror cover missing/ left fog light not working/ with LTO plate/