

General Information

Date & Time: 11, Feb, 2026 17:04

Make	Mitsubishi	Model	Xpander
YOM	2022	Odo Meter Reading	129,802
Registration No.	NFJ4466	Chassis No.	MK2LRNC1WNN004027
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.0	93	90	114
2	Boot Lid	89.8	89	99	82
3	Roof	90.3	103	97	83/78
4	Left Front Fender	82.5	80	86	81
5	Left Front Door	91.2	88	92	94
6	Center Panel Left				
7	Left Rear Door	86.8	79	91	91
8	Left Back Panel	95.8	100	100	88
9	Right Front Fender	76.6	78	79	73
10	Right Front Door	88.6	91	89	86
11	Center Panel Right				
12	Right Rear Door	87.0	87	86	88
13	Right Back Panel	92.2	99	90	88

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Small / Rear Seat - Grime - Large / Trunk Room - Worn, Scratch, Cut, Crack - Medium / (L) Rear Trim - Grime - Small / (L) Front Seat - Grime - Medium / Ceiling - Grime - Large / Dashboard - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/No spare key/with reverse camera/No seat cover/No warranty booklet/possibleflooding/with jack and incomplete tools/interior dirty</p>