

General Information

Date & Time: 18, Feb, 2026 11:09

Make	Mitsubishi	Model	Mirage
YOM	2025	Odo Meter Reading	7,777
Registration No.	NKM3998	Chassis No.	PAEA13RJSRA002373
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	122.6	124	125	119
2	Boot Lid	104.0	100	114	98
3	Roof	106.7	110	110	105/102
4	Left Front Fender	103.3	101	108	101
5	Left Front Door	108.0	109	109	106
6	Center Panel Left				
7	Left Rear Door	105.3	110	106	100
8	Left Back Panel	112.6	112	111	115
9	Right Front Fender	114.0	117	102	123
10	Right Front Door	110.3	112	109	110
11	Center Panel Right				
12	Right Rear Door	109.0	111	105	111
13	Right Back Panel	111.0	117	109	107

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Large / (L) Front Floor Mat - Worked - Large / Dashboard - Traces of Adhesive Tape - Yes</p>	<p>Remarks Bonnet - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Mirror - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>incomplete tools/ with warranty booklet and LTO plate/ with spare tire and jack/</p>