

General Information

Date & Time: 09, Feb, 2026 13:48

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	43,770
Registration No.	CCG3661	Chassis No.	PA1B18F3XR4264990
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	207.3	196	198	228
2	Boot Lid	111.6	110	100	125
3	Roof	203.5	232	170	245/167
4	Left Front Fender	147.6	156	164	123
5	Left Front Door	461.3	301	272	811
6	Center Panel Left				
7	Left Rear Door	514.6	957	249	338
8	Left Back Panel	512.3	1,058	293	186
9	Right Front Fender	785.3	292	1,175	889
10	Right Front Door	144.6	141	128	165
11	Center Panel Right				
12	Right Rear Door	105.3	104	106	106
13	Right Back Panel	102.4	98	101	108

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : B
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / Dashboard - Worn, Scratch, Cut, Crack - Large / Steering Wheel - Worn, Peel, Crack - Large / (L) Front Seat - Grime - Medium / (L) Front Trim - Grime - Minimal</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Overall Exterior - Full Re-Paint in same color - Yes / (R) Front Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Trunk Hood, Rear Gate - Modified - Medium</p>
Frame Evaluation : D	Functional Evaluation : C
<p>Remarks Front Cross Member Support - Condition of Welding ? - Yes / Right Front Inside Panel (Front Side) - Condition of Welding, Hardness and Shape of Sealant ? - Yes / Left Front Inside Panel (Front Side) - Condition of Welding, Hardness and Shape of Sealant ? - Yes / Left Front Inside (Rear Side) - Condition of Welding, Hardness and Shape of Sealant ? - Yes / Rear Side Member & Trunk Room Floor - Condition of Welding, Hardness and Shape of Sealant ? - Yes</p>	<p>Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes / Head Light, High Beam - Issue - Yes / Seat Belts - Issue - Yes / Spare Key - Issue - Unexist</p>

Inspector Notes
<p>With Lto plate, 1key, with warranty booklet, no spare tire, no jack and tools, scratches on headlights and taillights, battery weak, warning lamp on,air bag ,</p>