

General Information

Date & Time: 05, Feb, 2025 13:34

Make	Toyota	Model	Vios
YOM	2021	Mileage	37,429
Registration No.	NES4922	Chassis No.	PA1B18F35M4159928
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	109	108	113
2	Boot Lid	105.6	103	106	108
3	Roof	100.7	105	92	98/108
4	Left Front Fender	89.1	92	91	85
5	Left Front Door	93.1	93	97	90
6	Center Panel Left				
7	Left Rear Door	86.1	88	86	84
8	Left Back Panel	150.0	187	139	124
9	Right Front Fender	154.6	146	166	152
10	Right Front Door	87.9	85	88	91
11	Center Panel Right				
12	Right Rear Door	88.4	87	87	92
13	Right Back Panel	92.9	91	96	93

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Cut, Crack - Medium / Dashboard - Traces of Adhesive Tape - Yes	Remarks (R) Front Fender - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Bonnet, Headlight - Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch - Medium / (R) Rear Fender, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, spare tire,jack and tools. with LTO plate with plate cover. aftermarket head unit with 360 camera. aftermarket floormat and leather seat cover.