

General Information

Date & Time: 07, Feb, 2026 10:40

Make	Toyota	Model	Hiace
YOM	2025	Odo Meter Reading	40,086
Registration No.	CCG3258	Chassis No.	JTFJT02P2R5039041
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.6	109	126	130
2	Boot Lid	105.3	105	109	102
3	Roof	141.2	110	163	156/136
4	Left Front Fender	126.3	128	129	122
5	Left Front Door	104.3	107	104	102
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	103.7	104	99	108
9	Right Front Fender	116.0	113	113	122
10	Right Front Door	106.0	103	108	107
11	Center Panel Right	114.0	125	115	102
12	Right Rear Door	103.6	104	105	102
13	Right Back Panel	114.0	120	109	113

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	C
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Defects not found</p>		<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Center Panel - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Minimal</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes

With Lto plate, with warranty booklet, 1key, no spare tire, no jack and tools, scratches on headlights and taillights, front seat unjuster handle missing, fog light switch issue,