

## General Information

Date & Time: 13, Feb, 2026 13:50

<b>Make</b>	Mitsubishi	<b>Model</b>	L300
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	10,415
<b>Registration No.</b>	NKM2664	<b>Chassis No.</b>	PAEL65MYSRB029347
<b>CC</b>	2.2	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	FB Body
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	73.2	72	74	73
2	Boot Lid	69.3	77	64	67
3	Roof	80.1	68	119	65/69
4	Left Front Fender	85.6	79	93	85
5	Left Front Door	65.0	70	65	60
6	Center Panel Left	78.3	79	79	76
7	Left Rear Door	120.0	121	119	120
8	Left Back Panel	240.8	70	58	594
9	Right Front Fender	81.9	79	89	78
10	Right Front Door	60.0	61	57	62
11	Center Panel Right	73.6	76	73	72
12	Right Rear Door				
13	Right Back Panel	72.5	56	70	92

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

