

General Information

Date & Time: 18, Feb, 2026 17:37

Make	MG	Model	ZS
YOM	2024	Odo Meter Reading	38,960
Registration No.	NKD5079	Chassis No.	LSJW74U31PZ266469
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	138.3	137	134	144
2	Boot Lid	139.0	144	138	135
3	Roof	128.7	126	123	135/131
4	Left Front Fender	136.6	143	134	133
5	Left Front Door	137.6	137	133	143
6	Center Panel Left				
7	Left Rear Door	141.6	136	149	140
8	Left Back Panel	143.6	145	141	145
9	Right Front Fender	130.6	131	128	133
10	Right Front Door	140.3	143	136	142
11	Center Panel Right				
12	Right Rear Door	149.0	156	149	142
13	Right Back Panel	141.3	132	143	149

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : E	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Smell - Yes / (R) Rear Trim - Grime - Large / (L) Rear Trim - Grime - Large / (R) Front Trim - Grime - Large / (R) Front Seat - Grime - Large / (R) Front Floor Mat - Grime - Large / (L) Front Trim - Grime - Large / (L) Front Floor Mat - Grime - Large / (L) Front Seat - Grime - Large / Dashboard - Traces of Adhesive Tape - Yes</p>	<p>Remarks Front Bumper, Grille, Lamps - Crack, Gap - Large / (L) Front Fender, Molding - Crack, Gap - Medium / Bonnet, Headlight - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Crack, Gap - Large / (R) Front Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Large / Roof - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes / Remote Key & Smart entry - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet/ EPS warning light/ possible flooding/ fog light issue/ smart key issue/ plate light issue/ with jack and tools/ with spare tire and LTO plate/</p>