

General Information

Date & Time: 11, Feb, 2026 16:37

Make	Geely	Model	Emgrand
YOM	2023	Odo Meter Reading	17,644
Registration No.	ZAF2118	Chassis No.	LB3F31021PG008768
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.1	101	92	107
2	Boot Lid	103.2	109	102	99
3	Roof	116.7	109	102	139/117
4	Left Front Fender	111.6	103	111	121
5	Left Front Door	127.6	131	126	126
6	Center Panel Left				
7	Left Rear Door	123.0	124	125	120
8	Left Back Panel	127.6	137	133	113
9	Right Front Fender	119.6	125	118	116
10	Right Front Door	131.6	124	133	138
11	Center Panel Right				
12	Right Rear Door	127.0	122	132	127
13	Right Back Panel	126.0	113	132	133

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / Sunvisor, Sunglass Holder - Worked - Small</p>	<p>Remarks Roof - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Medium / Bonnet, Headlight - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with spare tire, with jack, with reverse camera, no spare key, no warranty and manual booklet, scratches on taillight and headlight.</p>