

## General Information

Date & Time: 23, Feb, 2026 17:42

<b>Make</b>	Hyundai	<b>Model</b>	Tucson
<b>YOM</b>	2012	<b>Odo Meter Reading</b>	154,762
<b>Registration No.</b>	TVO172	<b>Chassis No.</b>	KMHJU81BBBU460773
<b>CC</b>	2.0	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	SUV
<b>Colour</b>	Gray		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.6	125	128	106
2	Boot Lid	115.3	107	121	118
3	Roof	113.3	99	102	108/144
4	Left Front Fender	115.0	137	103	105
5	Left Front Door	110.4	95	111	125
6	Center Panel Left				
7	Left Rear Door	112.0	106	114	116
8	Left Back Panel	108.3	102	112	111
9	Right Front Fender	102.0	105	101	100
10	Right Front Door	114.0	113	120	109
11	Center Panel Right				
12	Right Rear Door	109.6	104	121	104
13	Right Back Panel	184.0	125	284	143

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Large / Knobs - Worn, Peel, Crack - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Medium / (L) Front Seat - Cut, Crack - Medium / Rear Seat - Grime - Small / (R) Rear Trim - Loose, Deformed - Small / (R) Front Seat - Cut, Crack - Minimal / Trunk Room - Loose, Deformed - Small</p>	<p><b>Remarks</b> (R) Rear Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Faded(Color, Gloss) - Yes / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Minimal / (R) Rear Fender, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / Roof Spoiler, Molding - Partially Missing - Yes / (L) Rear Fender, Molding - Scratch &amp; Dent - Small / Roof - Rust, Corrosion - Medium / (L) Rear Door, Molding - Scratch &amp; Dent - Small / (L) Mirror - Faded(Color, Gloss) - Yes / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch &amp; Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Minimal / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / Bonnet, Headlight - Scratch &amp; Dent - Minimal / Front Windshield - Scratch, Stone chip - Small / Rear Windshield - Scratch, Stone chip - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Door Lock - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With Lto plate, with warranty booklet, with spare tire, 1key, no jack and tools, scratches on headlights and taillights,</p>