

General Information

Date & Time: 10, Feb, 2026 15:39

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	34,787
Registration No.	HAG8734	Chassis No.	PA1B18F3XR4269123
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.0	125	116	116
2	Boot Lid	114.0	113	111	118
3	Roof	99.0	100	98	96/102
4	Left Front Fender	98.7	104	100	93
5	Left Front Door	101.3	100	100	104
6	Center Panel Left				
7	Left Rear Door	110.6	119	111	102
8	Left Back Panel	109.6	114	106	109
9	Right Front Fender	104.0	107	103	102
10	Right Front Door	104.6	108	104	102
11	Center Panel Right				
12	Right Rear Door	109.6	107	109	113
13	Right Back Panel	108.3	110	108	107

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / Ceiling - Grime - Minimal / Mat Other - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Possible flooding. Front emblem missing. With warranty booklet and spare tire.No jack and tools. 1 key. With LTO plate.</p>