

General Information

Date & Time: 10, Feb, 2026 13:15

Make	Toyota	Model	Lite Ace
YOM	2023	Odo Meter Reading	60,562
Registration No.	FAP1384	Chassis No.	MHKU3FE10PK0041
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	46.5	43	49	47
2	Boot Lid	56.7	67	44	59
3	Roof				
4	Left Front Fender	47.0	44	46	51
5	Left Front Door	46.9	51	49	41
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	62.5	62	65	60
9	Right Front Fender	52.4	56	48	53
10	Right Front Door	49.9	43	49	57
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	48.9	42	50	55

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Grime - Large / Ceiling - Grime - Small / (L) Front Seat - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks (R) Rear Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / (R) Side Gate - Scratch - Medium / (L) Guard Frame - Scratch - Small / Cargo Bed Floor - Scratch & Dent - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with spare tire. without jack and tools. no seat cover. with 2 spare keys</p>