

General Information

Date & Time: 11, Feb, 2026 12:59

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	15,643
Registration No.	DCA5893	Chassis No.	PA1B18F3XR4253360
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	167.6	173	154	176
2	Boot Lid	153.3	161	144	155
3	Roof	169.2	179	179	151/168
4	Left Front Fender	97.2	98	98	97
5	Left Front Door	99.7	101	105	93
6	Center Panel Left				
7	Left Rear Door	102.0	101	95	110
8	Left Back Panel	110.0	113	116	101
9	Right Front Fender	102.3	103	103	101
10	Right Front Door	122.3	118	121	128
11	Center Panel Right				
12	Right Rear Door	101.4	96	102	106
13	Right Back Panel	102.6	103	100	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Worked - Small / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Minimal / Ceiling - Grime - Minimal / Rear Seat - Grime - Small</p>	<p>Remarks (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / Trunk Hood, Rear Gate - Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Repair mark - Yes / Bonnet, Headlight - Crack, Gap - Medium / Roof - Scratch & Dent - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack, no tools, with spare tire, no LTO plate, scratches on tail light, headlight issue</p>