

General Information

Date & Time: 18, Feb, 2026 15:16

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	85,865
Registration No.	NHR2200	Chassis No.	PA1B18F38P4226686
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	156.0	144	171	153
2	Boot Lid	120.6	121	116	125
3	Roof	101.2	102	111	90/102
4	Left Front Fender	106.0	108	108	102
5	Left Front Door	167.6	172	169	162
6	Center Panel Left				
7	Left Rear Door	153.0	184	139	136
8	Left Back Panel	121.6	130	126	109
9	Right Front Fender	103.9	105	107	100
10	Right Front Door	106.6	109	108	103
11	Center Panel Right				
12	Right Rear Door	112.0	111	112	113
13	Right Back Panel	116.0	123	109	116

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Medium / Ceiling - Grime - Small / Overall Interior - Smell - Yes / Overall Interior - Worn as per age - Yes</p>	<p>Remarks (L) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Dent - Medium / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / Member (Bolted) - Dent - Yes / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet, no jack and tools, with spare tire, with LTO plate, scratches on tail light, possible flooding, plate light issue</p>