

General Information

Date & Time: 03, Mar, 2026 15:50

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	5,899
Registration No.	NHU8724	Chassis No.	PA1B18F33R4277614
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	116	102	114
2	Boot Lid	104.3	100	106	107
3	Roof	100.5	96	111	90/106
4	Left Front Fender	99.0	97	99	101
5	Left Front Door	100.0	104	98	98
6	Center Panel Left				
7	Left Rear Door	102.9	104	106	99
8	Left Back Panel	104.6	115	101	98
9	Right Front Fender	113.0	111	118	110
10	Right Front Door	104.0	110	99	103
11	Center Panel Right				
12	Right Rear Door	102.7	100	95	113
13	Right Back Panel	101.9	87	102	117

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : E	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Medium / Dashboard - Worn, Scratch, Cut, Crack - Medium / Rear Seat - Grime - Large / (R) Rear Trim - Grime - Medium / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Large / Steering Wheel - Worn, Peel, Crack - Medium / Ceiling - Grime - Medium / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small	Remarks (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate/with spare tire/with 2 spare key/No seat cover/possible flooding/left side tali cover issue/reverse camera issue/with jack and incomplete tools/No warranty booklet/