

General Information

Date & Time: 10, Feb, 2026 17:38

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	10,888
Registration No.	NKQ4997	Chassis No.	PA1B18F37S4285172
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.0	96	101	109
2	Boot Lid	94.2	85	94	103
3	Roof	92.7	98	92	84/97
4	Left Front Fender	92.8	90	93	96
5	Left Front Door	96.2	97	91	101
6	Center Panel Left				
7	Left Rear Door	97.0	100	97	94
8	Left Back Panel	98.2	102	99	94
9	Right Front Fender	93.6	96	91	94
10	Right Front Door	101.5	100	105	100
11	Center Panel Right				
12	Right Rear Door	101.0	102	101	100
13	Right Back Panel	104.8	98	109	108

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Small / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks Roof - Scratch - Large / (L) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>LTO plate not original/with spare tire/No spare key/with jack and incomplete tools/with reverse camera/with warranty booklet/No seat cover/</p>