

General Information

Date & Time: 18, Feb, 2026 15:08

Make	Toyota	Model	Rush
YOM	2022	Odo Meter Reading	15,261
Registration No.	DBF1964	Chassis No.	MHKE8FF3PMK035941
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Brown		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	106	103	121
2	Boot Lid	102.6	102	109	97
3	Roof	98.9	88	91	102/115
4	Left Front Fender	114.3	113	114	116
5	Left Front Door	116.6	120	113	117
6	Center Panel Left				
7	Left Rear Door	106.4	115	107	97
8	Left Back Panel	105.3	107	107	102
9	Right Front Fender	109.0	113	109	105
10	Right Front Door	107.6	105	109	109
11	Center Panel Right				
12	Right Rear Door	104.6	101	106	107
13	Right Back Panel	101.8	100	100	106

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	D
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Mat Other - Missing - Yes</p>		<p>Remarks (R) Rear Door, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Large / Trunk Hood, Rear Gate - Crack, Gap - Large / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Spare Key - Issue - Unexist</p>	

Inspector Notes
no warranty booklet/ no tools/ no jack/ with spare tire and LTO plate/