

General Information

Date & Time: 10, Feb, 2026 16:40

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	2,977
Registration No.	DCA4090	Chassis No.	PA1B18F39S4292642
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	118	101	115
2	Boot Lid	114.3	119	112	112
3	Roof	105.2	109	101	104/107
4	Left Front Fender	95.0	101	90	94
5	Left Front Door	107.3	117	103	102
6	Center Panel Left				
7	Left Rear Door	101.3	105	98	101
8	Left Back Panel	107.3	111	109	102
9	Right Front Fender	95.6	97	90	99
10	Right Front Door	101.9	99	101	106
11	Center Panel Right				
12	Right Rear Door	99.1	100	97	101
13	Right Back Panel	105.9	95	99	124

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Floor Mat - Grime - Small	Remarks (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
incomplete tools/ with jack and spare tire/ with LTO plate and warranty booklet