


General Information

Date & Time: 01, Feb, 2025 15:31

Make	Toyota	Model	Wigo
YOM	2024	Mileage	6,683
Registration No.	DBM6501	Chassis No.	MHKAA1BCXRJ01566
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	100	109	102
2	Boot Lid	84.8	81	86	88
3	Roof	84.8	86	81	87/85
4	Left Front Fender	92.0	86	90	100
5	Left Front Door	103.4	96	100	114
6	Center Panel Left				
7	Left Rear Door	97.1	103	93	96
8	Left Back Panel	89.1	86	94	88
9	Right Front Fender	92.2	99	99	78
10	Right Front Door	101.6	102	101	102
11	Center Panel Right				
12	Right Rear Door	96.8	92	99	100
13	Right Back Panel	93.7	97	97	88

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

with warranty booklet/ no tools and jack / with spare tire/ with LTO plate/ broken right tail light/