

General Information

Date & Time: 10, Feb, 2026 14:52

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	4,033
Registration No.	DCA3819	Chassis No.	PA1B18F32S4292725
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.3	117	105	103
2	Boot Lid	101.0	103	96	104
3	Roof	94.1	100	88	93/95
4	Left Front Fender	92.7	93	93	92
5	Left Front Door	101.0	103	100	100
6	Center Panel Left				
7	Left Rear Door	103.9	112	100	100
8	Left Back Panel	102.1	107	100	100
9	Right Front Fender	96.7	97	97	96
10	Right Front Door	94.3	92	97	94
11	Center Panel Right				
12	Right Rear Door	94.9	100	93	92
13	Right Back Panel	99.7	93	92	114

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Minimal</p>	<p>Remarks Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with 2 key/with jack and incomplete tools/with seat cover/with reverse camera/with warranty booklet</p>