

General Information

Date & Time: 10, Feb, 2026 17:28

Make	Toyota	Model	Veloz
YOM	2023	Odo Meter Reading	29,087
Registration No.	NFC7231	Chassis No.	MHFAB1BY0P3065385
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.0	104	102	106
2	Boot Lid	105.0	112	122	81
3	Roof	118.2	118	114	140/101
4	Left Front Fender	390.3	821	202	148
5	Left Front Door	113.6	111	107	123
6	Center Panel Left				
7	Left Rear Door	109.0	111	103	113
8	Left Back Panel	105.6	109	112	96
9	Right Front Fender	102.6	109	102	97
10	Right Front Door	106.0	108	103	107
11	Center Panel Right				
12	Right Rear Door	109.0	108	106	113
13	Right Back Panel	139.3	111	163	144

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Console, Switches, Vents - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Worked - Large / (R) Front Floor Mat - Grime - Medium</p>	<p>Remarks (R) Step - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Step - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Large / (L) Front Fender, Molding - Crack, Gap - Large / Bonnet, Headlight - Scratch - Large / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no tools/ with jack and spare tire/ with warranty booklet and LTO plate/</p>