

General Information

Date & Time: 13, Feb, 2026 09:04

Make	Toyota	Model	Veloz
YOM	2025	Odo Meter Reading	20,699
Registration No.	CCG6315	Chassis No.	MHFAB1BY9R315560
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.2	94	91	107
2	Boot Lid	102.0	106	110	90
3	Roof	110.8	124	118	102/99
4	Left Front Fender	95.6	95	97	95
5	Left Front Door	114.3	105	113	125
6	Center Panel Left				
7	Left Rear Door	111.0	114	102	117
8	Left Back Panel	116.0	125	120	103
9	Right Front Fender	96.5	95	98	96
10	Right Front Door	111.0	120	110	103
11	Center Panel Right				
12	Right Rear Door	109.6	111	107	111
13	Right Back Panel	120.6	122	113	127

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Grime - Small</p>	<p>Remarks (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Large / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Crack, Gap - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Dent - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, with spare tire and jack, no tools, scratches on headlights and taillights</p>