

General Information

Date & Time: 12, Feb, 2026 18:59

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	21,699
Registration No.	BAF4663	Chassis No.	PA1B18F36P4223849
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.8	125	86	97
2	Boot Lid	106.6	102	111	107
3	Roof	96.1	100	95	91/98
4	Left Front Fender	101.9	103	104	99
5	Left Front Door	105.3	102	108	106
6	Center Panel Left				
7	Left Rear Door	113.0	119	109	111
8	Left Back Panel	113.6	109	119	113
9	Right Front Fender	149.3	154	141	153
10	Right Front Door	137.6	139	136	138
11	Center Panel Right				
12	Right Rear Door	143.0	146	126	157
13	Right Back Panel	127.3	108	123	151

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Rear Seat - Grime - Large / Dashboard - Loose, Deformed - Large</p>		<p>Remarks Bonnet - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Roof - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Large / Front Windshield - Scratch, Stone chip - Medium</p>	
Frame Evaluation :	A	Functional Evaluation :	D
<p>Remarks Defects not found</p>		<p>Remarks Warning Lamps - Issue - Yes / Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Horn - Issue - Yes / Seat Belts - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes

With Lto plate, with jack and tools, 1key, no warranty booklet, no spare tire, scratches on headlights and taillights, dirt on engine, steering wheel modified, warning lamp on