

General Information

Date & Time: 02, Feb, 2025 14:31

Make	Toyota	Model	Vios
YOM	2022	Mileage	82,216
Registration No.	EAF3291	Chassis No.	PA1B18F30N4168537
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	131.0	123	133	137
2	Boot Lid	137.0	138	140	133
3	Roof	122.7	114	135	121/121
4	Left Front Fender	127.0	122	125	134
5	Left Front Door	131.0	135	128	130
6	Center Panel Left				
7	Left Rear Door	126.6	132	125	123
8	Left Back Panel	141.0	147	141	135
9	Right Front Fender	121.3	130	117	117
10	Right Front Door	129.0	125	120	142
11	Center Panel Right				
12	Right Rear Door	122.6	115	120	133
13	Right Back Panel	131.0	119	128	146

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Large / Rear Seat - Grime - Medium	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / Rear Bumper, Lamps, Panels - Dent - Medium / Trunk Hood, Rear Gate - Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / Bonnet, Headlight - Dent - Small / (L) Rear Door, Molding - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate number/jack/incomplete tools/no reverse camera/no spare tire