

General Information

Date & Time: 16, Feb, 2026 08:00

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	21,300
Registration No.	HAG8865	Chassis No.	PA1B18F39R4272496
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.3	114	104	101
2	Boot Lid	104.6	100	110	104
3	Roof	94.9	95	96	85/105
4	Left Front Fender	95.1	100	95	91
5	Left Front Door	129.3	117	128	143
6	Center Panel Left				
7	Left Rear Door	168.0	194	136	174
8	Left Back Panel	192.3	225	214	138
9	Right Front Fender	101.2	100	96	108
10	Right Front Door	99.8	103	98	99
11	Center Panel Right				
12	Right Rear Door	110.6	99	104	129
13	Right Back Panel	107.3	108	104	110

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	D	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Floor Mat - Grime - Large / (L) Front Trim - Grime - Small / Ceiling - Grime - Small / Sunvisor, Sunglass Holder - Grime - Small / Mat Other - Grime - Large / Rear Seat - Grime - Large / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Large</p>		<p>Remarks (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / (L) Front Fender, Molding - Scratch - Large / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Tyre - Crack, Cut - Yes / Trunk Hood, Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Large / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Medium / Roof - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Spare Key - Issue - Unexist</p>	

Inspector Notes

Punctured rear left tire. Rear left door and rear left fender repainted. Without warranty booklet. Incomplete tools. With spare tire, jack and leather seat cover. 1 key. With LTO plate.