

General Information

Date & Time: 13, Feb, 2026 12:56

Make	Toyota	Model	Vios
YOM	2019	Odo Meter Reading	65,140
Registration No.	NFT5919	Chassis No.	PA1B13F31K4095063
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	114	109	111
2	Boot Lid	193.6	235	168	178
3	Roof	94.0	104	93	88/92
4	Left Front Fender	96.2	103	94	92
5	Left Front Door	95.6	95	96	95
6	Center Panel Left				
7	Left Rear Door	140.0	157	136	127
8	Left Back Panel	148.0	178	123	143
9	Right Front Fender	110.3	107	107	117
10	Right Front Door	104.6	108	104	102
11	Center Panel Right				
12	Right Rear Door	158.6	125	224	127
13	Right Back Panel	103.2	100	99	111

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : E	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Large / (R) Front Seat - Grime - Medium / Sunvisor, Sunglass Holder - Grime - Small / Ceiling - Grime - Large / Rear Seat - Grime - Large / Mat Other - Grime - Large / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Large / (L) Front Floor Mat - Grime - Large / Console, Switchs, Vents - Traces of Adhesive Tape - Yes	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Bonnet, Headlight - Scratch - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Modified - Medium / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Small / Antennae - Stuck - Yes / Roof - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Parking Brake - Function - Weak

Inspector Notes
Possible flooding. Crack taillight. Scratches on headlight and taillight. Glove box loose. Trunk floor has a hole. Scratches at Antenna. Without warranty booklet, jack, tools and seat cover. With spare tire. 2 keys no remote. With LTO plate.