

General Information

Date & Time: 16, Feb, 2026 13:19

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	42,082
Registration No.	DBF7506	Chassis No.	PA1B18F30R4251049
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	117	108	113
2	Boot Lid	120.0	123	108	129
3	Roof	106.2	110	110	93/112
4	Left Front Fender	106.0	100	105	113
5	Left Front Door	100.9	102	101	100
6	Center Panel Left				
7	Left Rear Door	104.9	111	106	98
8	Left Back Panel	120.3	133	121	107
9	Right Front Fender	111.6	119	107	109
10	Right Front Door	110.3	118	105	108
11	Center Panel Right				
12	Right Rear Door	118.3	112	120	123
13	Right Back Panel	115.0	108	112	125

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Worn - Yes / Ceiling - Grime - Small</p>		<p>Remarks Roof - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Retractable Mirror - Issue - Yes</p>	

Inspector Notes
with LTO plate, with spare tire, with reverse camera, with manual and warranty booklet, with spare key, no tools and jack, issue on taillight lens, issue on sidemirror, scratches on headlight,.