

General Information

Date & Time: 16, Feb, 2026 10:46

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	12,523
Registration No.	NIO6032	Chassis No.	PA1B18F38P4219708
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.3	122	103	112
2	Boot Lid	122.3	116	124	127
3	Roof	114.0	108	125	111/112
4	Left Front Fender	104.3	103	103	107
5	Left Front Door	105.0	100	105	110
6	Center Panel Left				
7	Left Rear Door	111.0	114	113	106
8	Left Back Panel	112.3	117	108	112
9	Right Front Fender	135.0	147	150	108
10	Right Front Door	108.0	112	102	110
11	Center Panel Right				
12	Right Rear Door	112.3	108	112	117
13	Right Back Panel	105.3	106	103	107

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / Ceiling - Grime - Small</p>		<p>Remarks Roof - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate, with spare tire, with incomplete tools and jack, no reverse camera, no warranty and manual booklet, no spare key, scratches on taillight and headlight.