

## General Information

Date & Time: 16, Feb, 2026 12:27

<b>Make</b>	Toyota	<b>Model</b>	Hilux
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	4,141
<b>Registration No.</b>	NKT9879	<b>Chassis No.</b>	PAHACACA4S6426608
<b>CC</b>	2.4	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Utility Passenger
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	153.6	154	149	158
2	Boot Lid	72.9	82	68	69
3	Roof	179.2	185	183	172/177
4	Left Front Fender	150.6	153	148	151
5	Left Front Door	152.3	152	159	146
6	Center Panel Left	118.0	113	118	123
7	Left Rear Door	106.3	104	102	113
8	Left Back Panel	95.6	100	96	91
9	Right Front Fender	156.6	154	160	156
10	Right Front Door	127.0	125	127	129
11	Center Panel Right	100.1	102	101	97
12	Right Rear Door	86.3	82	81	96
13	Right Back Panel	96.0	97	83	108

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

