

General Information

Date & Time: 23, Feb, 2026 12:23

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	27,218
Registration No.	FAS2772	Chassis No.	PA1B18F35R4275041
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.9	95	97	105
2	Boot Lid	162.6	178	156	154
3	Roof	141.7	138	141	147/141
4	Left Front Fender	137.3	133	141	138
5	Left Front Door	84.0	81	84	87
6	Center Panel Left				
7	Left Rear Door	135.0	136	138	131
8	Left Back Panel	135.0	139	133	133
9	Right Front Fender	131.3	132	131	131
10	Right Front Door	143.3	135	145	150
11	Center Panel Right				
12	Right Rear Door	145.0	147	144	144
13	Right Back Panel	148.0	139	142	163

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Small / Ceiling - Grime - Small / (R) Rear Trim - Grime - Small / (R) Front Seat - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Small</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

Inspector Notes	
<p>No warranty booklet. no seat cover. with spare tire. with jack and tools. with 2 spare keys.</p>	