

General Information

Date & Time: 23, Feb, 2026 15:06

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	14,675
Registration No.	FAN9126	Chassis No.	PA1B18F31N4198713
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.0	108	104	100
2	Boot Lid	97.4	97	94	102
3	Roof	91.9	98	84	97/89
4	Left Front Fender	99.9	98	100	102
5	Left Front Door	95.2	104	90	92
6	Center Panel Left				
7	Left Rear Door	92.5	90	96	92
8	Left Back Panel	96.3	97	95	97
9	Right Front Fender	94.2	91	100	92
10	Right Front Door	96.0	97	105	86
11	Center Panel Right				
12	Right Rear Door	96.9	103	90	98
13	Right Back Panel	102.5	101	107	100

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Trim - Grime - Small / Rear Seat - Cigarette Burns - Burnt Minimal / Ceiling - Crinkle - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Medium</p>	<p>Remarks (R) Step - Repair Traces - Yes / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium</p>
Frame Evaluation : B	Functional Evaluation : B
<p>Remarks Center Floor Panel - Bulge (Cuts, Major Deforms) or Corrosion ? - Yes</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>No spare tire. with jack and tools. with seat cover.no warranty booklet. no spare key</p>