

## General Information

Date & Time: 17, Feb, 2026 08:49

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	10,434
<b>Registration No.</b>	GBK7661	<b>Chassis No.</b>	PA1B18F33S493009
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	134.3	172	100	131
2	Boot Lid	100.3	101	89	111
3	Roof	91.1	94	89	88/94
4	Left Front Fender	86.3	88	83	89
5	Left Front Door	93.8	91	93	98
6	Center Panel Left				
7	Left Rear Door	92.5	89	89	99
8	Left Back Panel	101.2	106	104	94
9	Right Front Fender	95.3	97	94	95
10	Right Front Door	95.0	95	97	93
11	Center Panel Right				
12	Right Rear Door	92.0	92	89	95
13	Right Back Panel	97.5	92	92	109

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>A</b>	<b>Exterior Evaluation :</b>	<b>B</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Minimal</p>		<p><b>Remarks</b> Bonnet - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / (L) Front Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Rear Fender, Molding - Dent - Minimal</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>B</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Battery - Weak - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
With Spare Tire. no Jack and tools. no LTO Plate. no spare key. with seat cover