

General Information

Date & Time: 17, Feb, 2026 11:02

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	2,328
Registration No.	NKS6716	Chassis No.	PAHAD9DA6S1627997
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Dropside
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	103	102	106
2	Boot Lid	110.0	116	100	114
3	Roof	103.7	107	106	100/102
4	Left Front Fender	107.0	101	108	112
5	Left Front Door	97.9	99	99	95
6	Center Panel Left	94.3	105	99	79
7	Left Rear Door				
8	Left Back Panel	93.8	88	82	111
9	Right Front Fender	111.3	116	114	104
10	Right Front Door	102.9	96	107	106
11	Center Panel Right	117.3	123	100	129
12	Right Rear Door				
13	Right Back Panel	105.0	120	98	97

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Defects not found</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Guard Frame - Scratch - Small / (R) Side Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Side Gate - Scratch - Minimal / Cargo Bed Floor - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, with spare tire and jack, 2keys, no tools, Crack headlight, scratches on taillights,</p>