

General Information

Date & Time: 17, Feb, 2026 15:31

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	87,551
Registration No.	NFD3673	Chassis No.	PA1B18F33N4169939
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	118	112	113
2	Boot Lid	109.0	112	101	114
3	Roof	93.5	109	91	83/91
4	Left Front Fender	98.4	98	99	98
5	Left Front Door	103.8	102	113	97
6	Center Panel Left				
7	Left Rear Door	102.0	98	108	100
8	Left Back Panel	109.0	107	107	113
9	Right Front Fender	98.5	100	99	97
10	Right Front Door	101.4	105	97	102
11	Center Panel Right				
12	Right Rear Door	98.8	90	94	112
13	Right Back Panel	103.1	108	97	104

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Small / (R) Front Trim - Grime - Small / Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Trunk Room - Repair Mark - Yes / Rear Seat - Grime - Medium</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / Roof - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch & Dent - Minimal / Front Windshield - Scratch, Stone chip - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, 1key, no spare tire, no jack and tools, scratches on headlights and taillights, room light issue, foul smell</p>