

General Information

Date & Time: 20, Feb, 2026 09:57

Make	Toyota	Model	Hiace
YOM	2022	Odo Meter Reading	295,439
Registration No.	GAW3228	Chassis No.	JTFNAFAP7M8023825
CC	2.8	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	132.6	136	126	136
2	Boot Lid	235.6	143	146	418
3	Roof	151.5	142	122	156/186
4	Left Front Fender	179.3	187	172	179
5	Left Front Door	150.6	150	137	165
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	173.3	181	165	174
9	Right Front Fender	149.0	143	156	148
10	Right Front Door	150.0	152	143	155
11	Center Panel Right	179.6	184	192	163
12	Right Rear Door	158.6	149	145	182
13	Right Back Panel	144.6	148	137	149

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	D	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
Remarks		Remarks	
<p>(L) Front Floor Mat - Grime - Large / Steering Wheel - Worn, Peel, Crack - Large / Console, Switches, Vents - Traces of Adhesive Tape - Yes / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Trim - Grime - Small / Ceiling - Grime - Large / Mat Other - Missing - Yes / (R) Front Floor Mat - Grime - Large / Overall Interior - Smell - Yes / Overall Interior - Animal Hair - Yes / (R) Front Trim - Grime - Small / Sunvisor, Sunglass Holder - Grime - Medium</p>		<p>(R) Step - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Center Panel - Repair Traces - Yes / (L) Front Fender, Molding - Scratch - Large / (L) Mirror - Scratch - Medium / (L) Front Door, Molding - Scratch - Large / (L) Center Panel - Scratch - Medium / (L) Rear Door, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Center Panel - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Crack - Damaged / Front Bumper, Grille, Lamps - Modified - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Overall Exterior - Faded(Color, Gloss) - Yes / Bonnet, Headlight - Scratch - Small</p>	
Frame Evaluation :	C	Functional Evaluation :	E
Remarks		Remarks	
<p>Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Rear Side Member & Trunk Room Floor - Traces of Bending, or Marks of Panel Repair ? - Yes</p>		<p>Warning Lamps - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Power Steering - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist</p>	

Inspector Notes
<p>Possible flooding. foul smell. Battery for replacement. Airbag warning lamp on. Crack left taillight. Damaged right side mirror. Scratches on headlight and taillight. front right side window switch working. Window master switch for front right window not working. Front right window open. Without warranty booklet, tools and jack. With spare tire and leather seat cover. 1 key. No LTO plate only with temporary plate.</p>