

General Information

Date & Time: 23, Feb, 2026 13:09

Make	Toyota	Model	Vios
YOM	2021	Odo Meter Reading	49,368
Registration No.	DAV3029	Chassis No.	PA1B18F36M4143723
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.1	111	94	107
2	Boot Lid	102.2	97	102	108
3	Roof	91.8	103	90	89/85
4	Left Front Fender	96.3	94	96	99
5	Left Front Door	98.0	106	99	90
6	Center Panel Left				
7	Left Rear Door	101.8	99	104	103
8	Left Back Panel	110.0	119	103	108
9	Right Front Fender	99.8	101	102	97
10	Right Front Door	101.0	100	102	101
11	Center Panel Right				
12	Right Rear Door	101.6	95	103	107
13	Right Back Panel	102.7	97	102	109

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Medium / Rear Seat - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Large / (L) Front Seat - Grime - Medium / Ceiling - Grime - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Dashboard - Worn, Scratch, Cut, Crack - Small	Remarks (L) Rear Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / Roof - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/No spare key/ No warranty booklet/No reverse camera/with seat cover/with jack and incomplete tools/