

General Information

Date & Time: 19, Feb, 2026 15:20

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	22,398
Registration No.	DBT9360	Chassis No.	PA1B18F30S4286938
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	106	112	110
2	Boot Lid	102.9	96	101	112
3	Roof	98.9	98	107	94/97
4	Left Front Fender	96.0	94	96	98
5	Left Front Door	100.2	102	102	97
6	Center Panel Left				
7	Left Rear Door	94.8	99	95	91
8	Left Back Panel	100.1	105	103	93
9	Right Front Fender	103.0	101	103	105
10	Right Front Door	98.4	103	94	98
11	Center Panel Right				
12	Right Rear Door	101.6	100	101	104
13	Right Back Panel	97.8	101	96	97

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Worn - Yes / Ceiling - Grime - Minimal / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal / Rear Seat - Grime - Minimal / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Horn - Issue - Yes</p>

Inspector Notes
<p>with warranty booklet, jack and tools, with spare tire, with LTO plate, scratches on tail light, horn issue</p>