

## General Information

Date & Time: 20, Feb, 2026 09:47

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2022	<b>Odo Meter Reading</b>	182,706
<b>Registration No.</b>	NID3785	<b>Chassis No.</b>	PA1B18F39N4184199
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.3	103	96	126
2	Boot Lid	111.0	110	115	108
3	Roof	98.5	102	97	97/98
4	Left Front Fender	282.0	146	494	206
5	Left Front Door	415.3	980	130	136
6	Center Panel Left				
7	Left Rear Door	113.6	113	117	111
8	Left Back Panel	111.0	117	108	108
9	Right Front Fender	99.9	100	101	99
10	Right Front Door	113.0	117	112	110
11	Center Panel Right				
12	Right Rear Door	109.3	111	105	112
13	Right Back Panel	105.3	106	102	108

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

