

General Information

Date & Time: 18, Feb, 2026 18:55

Make	Toyota	Model	Rush
YOM	2021	Odo Meter Reading	37,222
Registration No.	NGL6044	Chassis No.	MHKE8FF3PMK031903
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.0	118	126	119
2	Boot Lid	103.7	103	98	110
3	Roof	93.1	87	79	105/102
4	Left Front Fender	111.0	111	114	108
5	Left Front Door	113.3	110	116	114
6	Center Panel Left				
7	Left Rear Door	123.6	120	121	130
8	Left Back Panel	114.0	109	113	120
9	Right Front Fender	108.0	108	107	109
10	Right Front Door	111.0	111	115	107
11	Center Panel Right				
12	Right Rear Door	106.4	109	111	99
13	Right Back Panel	117.0	136	111	104

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Small / Mat Other - Worked - Small / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / (R) Rear Trim - Grime - Minimal / Rear Seat - Grime - Small / Ceiling - Crinkle - Minimal</p>	<p>Remarks (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light, shift knob missing</p>