

General Information

Date & Time: 21, Feb, 2026 08:49

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	87,101
Registration No.	EAF1013	Chassis No.	PA1B18F35N4169358
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.0	118	106	103
2	Boot Lid	102.2	109	93	105
3	Roof	84.0	92	83	79/82
4	Left Front Fender	88.5	89	92	85
5	Left Front Door	91.3	86	99	89
6	Center Panel Left				
7	Left Rear Door	311.0	640	177	116
8	Left Back Panel	102.1	111	98	98
9	Right Front Fender	96.5	102	96	92
10	Right Front Door	144.3	140	135	158
11	Center Panel Right				
12	Right Rear Door	167.0	160	142	199
13	Right Back Panel	280.0	313	176	351

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Cut, Crack - Medium / (L) Front Floor Mat - Cut, Crack - Small / Mat Other - Missing - Yes / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / (L) Rear Trim - Missing - Yes</p>	<p>Remarks (R) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Door, Molding - Repair mark - Difference in Color / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / Front Windshield - Scratch, Stone chip - Medium / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With Lto plate, 1key, no warranty booklet, no spare tire, no jack and tools, scratches on headlights and taillights, battery weak, plate light issue, L rear door issue</p>