

## General Information

Date & Time: 23, Feb, 2026 12:49

<b>Make</b>	Toyota	<b>Model</b>	Hiace
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	31,292
<b>Registration No.</b>	DBO7293	<b>Chassis No.</b>	JTFPA9AP5R8043055
<b>CC</b>	2.8	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Van
<b>Colour</b>	Pearl White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	135.6	141	125	141
2	Boot Lid	113.3	111	112	117
3	Roof	130.7	140	138	114/131
4	Left Front Fender	116.3	110	125	114
5	Left Front Door	129.3	137	128	123
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	119.3	113	123	122
9	Right Front Fender	121.3	114	129	121
10	Right Front Door	129.0	121	131	135
11	Center Panel Right	146.3	152	151	136
12	Right Rear Door	130.0	122	133	135
13	Right Back Panel	137.6	132	134	147

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	C	<b>Exterior Evaluation :</b>	C
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Ceiling - Grime - Large</p>		<p><b>Remarks</b> (R) Front Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch - Medium / Roof - Dent - Medium</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
no warranty booklet/ no tools/ with jack and spare tire/ with LTO plate/