

General Information

Date & Time: 24, Feb, 2026 15:44

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	54,630
Registration No.	GAR8763	Chassis No.	PA1B18F37N4182810
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	110	110	110
2	Boot Lid	110.6	107	112	113
3	Roof	96.9	96	99	96/97
4	Left Front Fender	98.1	100	98	97
5	Left Front Door	106.6	101	109	110
6	Center Panel Left				
7	Left Rear Door	100.7	105	99	98
8	Left Back Panel	107.6	113	106	104
9	Right Front Fender	99.6	100	96	103
10	Right Front Door	106.0	104	109	105
11	Center Panel Right				
12	Right Rear Door	107.0	108	106	107
13	Right Back Panel	111.6	105	108	122

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Small / Ceiling - Grime - Medium / Sunvisor, Sunglass Holder - Grime - Small / Mat Other - Grime - Large / Rear Seat - Grime - Small / (R) Front Trim - Grime - Medium / (R) Front Floor Mat - Grime - Medium</p>	<p>Remarks (L) Front Fender, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Large / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Scratch - Large</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Front grille issue loose. Gap at trunk door. With warranty booklet, spare tire, jack and seat cover. Incomplete tools. 1 key. With LTO plate.</p>