

General Information

Date & Time: 23, Feb, 2026 15:58

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	2,247
Registration No.	CCQ6838	Chassis No.	PAHACACA6S6429932
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.6	101	112	122
2	Boot Lid	60.1	73	53	54
3	Roof	132.2	201	114	109/105
4	Left Front Fender	106.3	111	108	100
5	Left Front Door	101.3	101	105	98
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	73.3	64	87	70
9	Right Front Fender	109.3	106	112	110
10	Right Front Door	107.0	100	105	116
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	77.2	76	89	66

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Grime - Minimal / (R) Front Floor Mat - Grime - Minimal / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Minimal</p>	<p>Remarks Roof - Repair Traces - Yes / Bonnet, Headlight - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Side Gate - Scratch & Dent - Small / Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Guard Frame - Scratch & Dent - Medium / (R) Side Gate - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Roof - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / Cargo Bed Floor - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate, with Manual and warranty booklet, with spare tire, with tools & jack, scratches on taillight and headlight,</p>