

General Information

Date & Time: 21, Feb, 2026 19:40

Make	Toyota	Model	Veloz
YOM	2023	Odo Meter Reading	47,114
Registration No.	NIO3326	Chassis No.	MHFAB1BY2P3061838
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.1	96	98	98
2	Boot Lid	213.0	238	203	198
3	Roof	99.6	104	109	91/95
4	Left Front Fender	97.0	96	95	100
5	Left Front Door	107.0	103	102	116
6	Center Panel Left				
7	Left Rear Door	97.3	103	94	96
8	Left Back Panel	107.0	115	105	101
9	Right Front Fender	99.5	108	97	94
10	Right Front Door	106.0	109	105	104
11	Center Panel Right				
12	Right Rear Door	106.6	102	104	114
13	Right Back Panel	118.0	114	112	128

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Overall Interior - Smell - Yes	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Large / (L) Front Door, Molding - Scratch - Large / Trunk Hood, Rear Gate - Repair mark - Yes / (L) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Crack, Gap - Large / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Large / Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet/ no tools and jack/ with LTO plate and sparetire/